Tach circuit for V2.98 and higher



Note this was tested with V2.98 code and Bosch Solid-state ignition - Peter Florance

Revised 02/15/2005 - Corrected orientation of diode in U4

Dave Cap